



# RELIABLE CORPORATION PRODUCT COMPARISON CHART



## MOTORS

MODEL	POWER	POWER CONSUMPTION	POWER EFFICIENCY	TORQUE	SPEED	STARTING CURRENT	ON/OFF SWITCH	REVERSE SWITCH
<b>CLUTCH</b> 	1/2 hp - 400W	5.8 amps	61%	Base	Low speed and high speed models required.	9 amp	Separate switch required.	√
<b>SQ4000</b> 	1/2 hp - 400W	3.5 amps	96%	80% More torque on standard machines.	One motor for all machine types.	0	Built-in	√